




Measuring your Hand for Mitt Sizing in Inches/Centimeters

Circumference



Circumference: Without including your thumb, measure just above the thumb, around the hand. Measure with tape loose, do not tighten tape around the hand.

Length



Length: Tip of longest Finger to the break of the wrist.

Gloves/Mitts		in Centimeters						
Circumference		17.5	19	20	21.5	23	24	25.5
Length		17	18	19	20	22	23	23 24
Gloves/Mitts		in Inches						
Circumference		7	7.5	8	8.5	9	9.5	9.5 10+
Length		6.5	7	7.5	8	8.5	9	9 9.5+
Euro Size		6.5	7	7.5	8	8.5	9	9.5
US Size		S	M		L		XL	